CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number	Corrected
HYSTER COMPANY	E40XN	2017	A269N03360R	A269N03360R
Mast	3 Stage FFL (Triplex)	<u> </u>	Hours	14740 Inspected
Mast Height Lowered	82		Voltage	36 Volt
Mast Height Raised	187		Attachment	Carton Clamp
Hydraulic Control Valve	4-Function		Directional Control	Monotrol
Capacity	4000		Tires	Cushion
Mast Condition	Inspected		Steering Pump Condition	Inspected
Mast Comments	Inspected		Steering Pump Comments	mspected
Lift Cylinder Condition	Ingrested		Hydraulic Pump Condition	Lucus actad
Lift Cylinder Comments	Inspected		Hydraulic Pump Comments	Inspected
Tilt Cylinder Condition	T., .,		Hydraulic Motor Condition	I., .,,
Tilt Cylinder Comments	Inspected		Hydraulic Motor Comments	Inspected
Carriage Condition	T., 4. 1		Control System Condition	1 4 1
Carriage Comments	Inspected		Control System Comments	Inspected
Load Backrest Condition			Control System Comments	
Load Backrest Comments			Drive Motor Condition	
				Inspected
Forks Comments			Drive Motor Comments	
Forks Comments			Differential Condition	Inspected
Overally and Overall Consulting			Differential Comments	
Overhead Guard Condition	Inspected		Drive Tires % Remaining	
Overhead Guard Comments			Drive Tires Condition	Chunked
0 40 100	5		Steer Tires % Remaining	70%
Seat Condition	Damaged		Steer Tires Condition	Inspected
Seat Comments	torn		Steer Axle Condition	Inspected
			Steer Axle Comments	
General Appearance Condition	Fair		Brakes Condition	Inspected
General Appearance Comments	Impact damage		Brakes Comments	
General Comments			Battery Present	Yes
right hand header hoses chaffed, main lift hose chaffed, play in control valve linkage, fourth function plastic taped			Charger Present	Yes
together, trunion bushings worn, clamp bushings worn, clamp cylinders drift apart, freelift chains worn out, battery dirty, steer pins and bushings worn, steer wheel bearings need to be repacked		Florida I Ocalifica		
		Electrical Condition	Inspected	
			Electrical Comments	

Inspector Company Name	Eastern Lift Truck	Inspection Date	2/8/2023 10:16:06 AM
Inspector Name	jpellini		























