CONDITION REPORT - INTERNAL COMBUSTION


| Manufacturer | Model Year | Serial Number | |
|--|---|-------------------------------------|------------------------|
| HYSTER COMPANY | H50FT 2014 | N177V01671M | |
| | | | |
| Mast | | Hours | 3768 |
| Mast Height Lowered | 82 | Fuel | |
| Mast Height Raised | | Attachment | |
| Hydraulic Control Valve | | Directional Control | |
| Capacity | | Tires | |
| Mast Condition | | Engine | |
| Mast Comments | | Engine Inspected Condition | |
| Lift Cylinder Condition | | Engine Inspected Comments | |
| Lift Cylinder Comments | | Radiator Condition | |
| Tilt Cylinder Condition | | Radiator Comments | |
| Tilt Cylinder Comments | | Transmission/MDU Condition | |
| Carriage Condition | Tight / loose | Transmission/MDU Comments | |
| Carriage Comments | Bent/broken | | |
| Load Backrest Condition | Missing | Steering Pump Condition | |
| Load Backrest Comments | Need to install | Steering Pump Comments | |
| Forks Condition | Bent / warped / damaged | Hydraulic Pump Condition | |
| Forks Comments | | | |
| | Need to be replaced | Hydraulic Pump Comments | |
| | | Hydraulic Motor Condition | |
| Overhead Guard Condition | | Hydraulic Motor Comments | |
| Overhead Guard Comments | | Control System Condition | |
| | | Control System Comments | |
| Seat Condition | | | |
| Seat Comments | | Differential Condition | |
| | | Differential Comments | |
| General Appearance Condition | Fair | Drive Tires % Remaining | 70 |
| General Appearance Comments | | Drive Tires Condition | |
| | | Steer Tires % Remaining | 70 |
| General Comments | | Steer Tires Condition | |
| Inspected by Neal Fischer 09/05/19 - Har | d copy of inspection under images tab. Carriage is bent. Ho | ses need to be Steer Axle Condition | |
| replaced - forks need to be replaced. | | Steer Axle Comments | |
| | | Brakes Condition | |
| | | Brakes Comments | |
| | | Electrical Condition | |
| | | Electrical Comments | |
| | | | |
| | | | |
| | | | |
| | | | |
| Inspector Company Name | Eastern Lift Truck | Inspection Date | 11/26/2019 10:04:08 AM |
| Inspector Company Name | Wondy Davia | moposition Bato | |


Inspector Name

Wendy Davis









| A WARNING | | | | | |
|---|----------------------|------------------------|-------------------|---------------------------------|-----|
| Trained Operators and Mechanics Only | | | | | |
| Read Operation Manual locate on seat or in | | | | | |
| operators compartment ailure to follow operating, | Tire Fro | Service Statistics | | <u>Rear</u> 3.00X9/4.0 Solid | |
| nspection, and maintenance Instructions can cause | MAXIMUM CAPACITY | Load Height Dint. A | Load Dim. B | Center Dim. C | |
| erious injury or death! CAPACITY WITH MAST | 2090 kg (4600 lb) | 4800mm (189 in) | 610 mm (24 in) | 610 mm (24 in) | BI- |
| VERTICAL AND EQUIPPED AS SHOWN | 2180 kg (4800 lb) | 4350 mm (171.3 in) | 610 mm (24 in) | 610 mm (24 in) | |

