



Aspen Field Services

Job #: 18065

Unit #: 400-9866020-001-3464375



## 2009 HYSTER E35Z / 400-9866020-001-3464375

Inspection Questions	
Make	Hyster
Model	E35Z
Serial Number	F114N02571G
Type	Fork Lift
Inspection Date	11/05/19
Location of Business	5210 Shirley Drive Tyler, TX 75708
Attachment(s)/ Accessory(s)	NA
2-Speed	
Enclosed Cab	No
Engine MFR	Battery
Controls	Selectable Joystick Controls, Foot Control
High Flow Hydraulics-Sticker	
Hours	NA
Cab A-C	No
Cab Heat	No
Power Bob-Tach	
Hydraulic X-Change (only for Excavators)	
Backup Camera	No
Ride Control	
Deluxe Instrumentation	No
Keyless Start	No
Visual Inspection	Clean
Operational Test	Does not Start
Front Right Tire Part Number	None Printed
Front Right Tire Depth Percentage	40-49%
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	2 1/2"
Front Left Tire Part Number	None Printed
Front Left Tire Depth Percentage	40-49%
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	2 5/8"
Back Right Tire Part	None Printed





# Aspen Field Services

Job #: 18065 / 11-05-2019

VIN: F114N02571G

Number	
Back Right Depth Percentage	40-49%
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	2 5/8"
Back Left Tire Part Number	None Printed
Back Left Tire Depth Percentage	40-49%
Back Left Tire Condition	Gauge
Back Left Tire Depth Measurement	2 5/8"
Left Track Part Number	NA
Left Track Depth Percentage	NA
Left Track Condition	NA
Left Track Depth Measurement	NA
Right Track Part Number	NA
Right Track Depth Percentage	NA
Right Track Condition	NA
Right Track Depth Measurement	NA
Tilt Cylinders	No Leaks
Lift Cylinders	No Leaks
Boom Arms Operations	
Seat	Tear
Tailgate Lights	Non operational
Working Lights	Non Operational
Front Door	NA
Side Glass Complete	NA
Boom Arms Damages	
Rear Door	
Mufflers	
ROPS Condition	Good Condition
Power Bob-Tach Condition	NA
Cab A-C Condition	NA
Cab Heat Condition	NA
Intake Screen	



## Aspen Field Services

Job #: 18065 / 11-05-2019

VIN: F114N02571G

Interior	Fair
Engine Compartment	Good
Hydraulic X-Change Condition (only for Excavators)	
Customer Decals Visible on Unit	No
Comments	The battery is dead and can not be charged to view hours and display screen. The forklift can not be seen in operation or move. The equipment is located next to another piece of machinery and can not be moved to better view the left rear tire and any of the left side of the equipment clearly. The forks that came with the machine are not installed or on site.

# Aspen Field Services



Front / 11-05-2019

# Aspen Field Services



Side / 11-05-2019

# Aspen Field Services



Side / 11-05-2019

# Aspen Field Services



Rear / 11-05-2019



# Aspen Field Services



Serial Plate / 11-05-2019



No Forks / 11-05-2019

# Aspen Field Services



ROPS / 11-05-2019

# Aspen Field Services



ROPS Right / 11-05-2019

# Aspen Field Services



ROPS Top / 11-05-2019

# Aspen Field Services



ROPS / 11-05-2019

# Aspen Field Services



ROPS Left / 11-05-2019

# Aspen Field Services



Tilt Cylinder Left / 11-05-2019

# Aspen Field Services



Tilt Cylinder Right / 11-05-2019



# Aspen Field Services



Battery / 11-05-2019

# Aspen Field Services



LBR / 11-05-2019



Mast / 11-05-2019

# Aspen Field Services



Mast / 11-05-2019



Hydraulics / 11-05-2019

# Aspen Field Services



Hydraulics / 11-05-2019

# Aspen Field Services



Chains/Hydraulics / 11-05-2019

# Aspen Field Services



Rust / 11-05-2019

# Aspen Field Services



Paint Damage / 11-05-2019

# Aspen Field Services



Front Right Tire / 11-05-2019



Front Right Tire Size / 11-05-2019



# Aspen Field Services



Front Right Tire Depth / 11-05-2019



Right Rear Tire / 11-05-2019

# Aspen Field Services



Front Left Tire / 11-05-2019



Front Left Tire Size / 11-05-2019

# Aspen Field Services



Front Left Tire Depth / 11-05-2019

# Aspen Field Services



Back Left Tire / 11-05-2019

# Aspen Field Services



Back Left Tire Size / 11-05-2019

# Aspen Field Services



Back Left Tire Depth / 11-05-2019

# Aspen Field Services



Seat / 11-05-2019

# Aspen Field Services



Seat (Tear) / 11-05-2019



Display Screen / 11-05-2019



# Aspen Field Services



Controls / 11-05-2019



Pedals / 11-05-2019

# Aspen Field Services



Steering Wheel / 11-05-2019