

CONDITION REPORT - INTERNAL COMBUSTION

| Manufacturer | Model | Year | Serial Number |
|----------------|-------|------|---------------|
| HYSTER COMPANY | H80FT | 2014 | S005V03453M |

| | | | |
|-------------------------|-----------------------|---------------------|-----------------|
| Mast | 3 Stage FFL (Triplex) | Hours | 5196 |
| Mast Height Lowered | 89 | Fuel | Diesel |
| Mast Height Raised | 186 | Attachment | Other |
| Hydraulic Control Valve | 4-Function | Directional Control | Monotrol |
| Capacity | 8000 | Tires | Solid Pneumatic |

| | | | |
|--|--------------------|----------------------------|--------|
| Mast Condition | | Engine | Kubota |
| Mast Comments | | Engine Inspected Condition | |
| Lift Cylinder Condition | | Engine Inspected Comments | |
| Lift Cylinder Comments | | Radiator Condition | |
| Tilt Cylinder Condition | | Radiator Comments | |
| Tilt Cylinder Comments | | Transmission/MDU Condition | |
| Carriage Condition | Tight / loose | Transmission/MDU Comments | |
| Carriage Comments | Needs shims | | |
| Load Backrest Condition | | Steering Pump Condition | |
| Load Backrest Comments | | Steering Pump Comments | |
| Forks Condition | | Hydraulic Pump Condition | |
| Forks Comments | | Hydraulic Pump Comments | |
| | | Hydraulic Motor Condition | |
| Overhead Guard Condition | | Hydraulic Motor Comments | |
| Overhead Guard Comments | | Control System Condition | |
| | | Control System Comments | |
| Seat Condition | | | |
| Seat Comments | | Differential Condition | |
| | | Differential Comments | |
| General Appearance Condition | Good | Drive Tires % Remaining | |
| General Appearance Comments | Sheet metal damage | Drive Tires Condition | |
| | | Steer Tires % Remaining | 60 |
| General Comments | | Steer Tires Condition | |
| <div style="border: 1px solid black; padding: 5px;"> Drive tire about 60 % use. right front fender bent up position. left fender bent Down on corner. hdy. fan stuck on </div> | | Steer Axle Condition | |
| | | Steer Axle Comments | |
| | | Brakes Condition | |
| | | Brakes Comments | |
| | | Electrical Condition | |
| | | Electrical Comments | |

| | | | |
|------------------------|----------------------|-----------------|---------------------|
| Inspector Company Name | Deep South Equipment | Inspection Date | 8/4/2020 9:14:52 AM |
| Inspector Name | Gharrison | | |

(* Legend: =Checked OK)







