## **CONDITION REPORT - INTERNAL COMBUSTION**

| Manufacturer                 | Model                 | Year | Serial Number              |                 |
|------------------------------|-----------------------|------|----------------------------|-----------------|
| YALE MANUFACTURER            | GP060VX               | 2013 | B875V13364L                |                 |
|                              |                       |      |                            |                 |
| Mast                         | 3 Stage FFL (Triplex) |      | Hours                      | 6407            |
| Mast Height Lowered          | 87                    |      | Fuel                       | Diesel          |
| Mast Height Raised           | 181.9                 |      | Attachment                 | Side Shifter    |
| Hydraulic Control Valve      | 3-Function            |      | Directional Control        | Lever           |
| Capacity                     | 6000                  |      | Tires                      | Solid Pneumatic |
| Mast Condition               |                       |      | Engine                     | Kobota          |
| Mast Comments                |                       |      | Engine Inspected Condition | Νουσια          |
| Lift Cylinder Condition      |                       |      | Engine Inspected Comments  |                 |
| Lift Cylinder Comments       |                       |      | Radiator Condition         |                 |
| Tilt Cylinder Condition      |                       |      | Radiator Comments          |                 |
| Tilt Cylinder Comments       |                       |      | Transmission/MDU Condition |                 |
| Carriage Condition           |                       |      | Transmission/MDU Comments  |                 |
| Carriage Comments            |                       |      | Transmission/MDO Comments  |                 |
| Load Backrest Condition      |                       |      | Steering Pump Condition    |                 |
| Load Backrest Comments       |                       |      | Steering Pump Comments     |                 |
| Forks Condition              |                       |      | Hydraulic Pump Condition   |                 |
| Forks Comments               |                       |      | Hydraulic Pump Comments    |                 |
| Torks Comments               |                       |      | Hydraulic Motor Condition  |                 |
| Overhead Guard Condition     |                       |      | Hydraulic Motor Comments   |                 |
| Overhead Guard Comments      |                       |      | Control System Condition   |                 |
| Overnead Guard Comments      |                       |      | Control System Comments    |                 |
| Seat Condition               | Damaged               |      | Control System Comments    |                 |
| Seat Comments                | Damaged               |      | Differential Condition     |                 |
| Coat Comments                |                       |      | Differential Comments      |                 |
| General Appearance Condition |                       |      | Drive Tires % Remaining    | 30              |
| General Appearance Comments  |                       |      | Drive Tires Condition      | 50              |
| Contra Appearance Comments   |                       |      | Steer Tires % Remaining    | 70              |
| General Comments             |                       |      | Steer Tires Condition      | 70              |
| Control Comments             |                       |      | Steer Axle Condition       |                 |
|                              |                       |      | Steer Axle Comments        |                 |
|                              |                       |      | Brakes Condition           |                 |
|                              |                       |      | Brakes Comments            |                 |
|                              |                       |      | _iano commonto             |                 |
|                              |                       |      | Electrical Condition       |                 |
|                              |                       |      | Electrical Comments        |                 |
|                              |                       |      | _loomodi commonto          |                 |
|                              |                       |      |                            |                 |
|                              |                       |      |                            |                 |
|                              |                       |      |                            |                 |
|                              |                       |      |                            |                 |
|                              |                       |      |                            |                 |

| Inspector Company Name | Briggs equipment | Inspection Date | 7/30/2019 11:33:28 AM |
|------------------------|------------------|-----------------|-----------------------|
| Inspector Name         | David Ward       |                 |                       |





