

# CONDITION REPORT - INTERNAL COMBUSTION

<b>Manufacturer</b>	<b>Model</b>	<b>Year</b>	<b>Serial Number</b>
<b>HYSTER COMPANY</b>	<b>H80FT</b>	<b>2014</b>	<b>S005V03454M</b>

Mast	3 Stage FFL (Triplex)	Hours	6005
Mast Height Lowered	89	Fuel	Diesel
Mast Height Raised	173	Attachment	Other
Hydraulic Control Valve	4-Function	Directional Control	Monotrol
Capacity	8000	Tires	Solid Pneumatic

Mast Condition		Engine	Kubota
Mast Comments		Engine Inspected Condition	
Lift Cylinder Condition		Engine Inspected Comments	
Lift Cylinder Comments		Radiator Condition	
Tilt Cylinder Condition		Radiator Comments	
Tilt Cylinder Comments		Transmission/MDU Condition	
Carriage Condition	Tight / loose	Transmission/MDU Comments	
Carriage Comments	Needs shims		
Load Backrest Condition	Not applicable	Steering Pump Condition	
Load Backrest Comments	na	Steering Pump Comments	
Forks Condition	Not applicable	Hydraulic Pump Condition	
Forks Comments	na	Hydraulic Pump Comments	
		Hydraulic Motor Condition	
Overhead Guard Condition		Hydraulic Motor Comments	
Overhead Guard Comments		Control System Condition	
		Control System Comments	
Seat Condition	Damaged		
Seat Comments	bottom seat cushion torn on corner	Differential Condition	
		Differential Comments	
General Appearance Condition	Good	Drive Tires % Remaining	50
General Appearance Comments	Sheet metal damage	Drive Tires Condition	
		Steer Tires % Remaining	40
General Comments		Steer Tires Condition	Not-Selected
		Steer Axle Condition	
		Steer Axle Comments	
		Brakes Condition	
		Brakes Comments	
		Electrical Condition	
		Electrical Comments	

Inspector Company Name	Deep SouthEquipment	Inspection Date	8/4/2020 9:30:41 AM
Inspector Name	Gary Harrison		

(\* Legend: =Checked OK)





