


CONDITION REPORT - ELECTRIC

| | | | | | | | |
|--|--|----------------|--|---------------------------|--|----------------------|--|
| Manufacturer | | Model | | Year | | Serial Number | |
| YALE MANUFACTURER | | MPE080-VG | | 2016 | | B287N02307P | |
| Mast | | | | Hours | | 5533 | |
| Mast Height Lowered | | | | Voltage | | | |
| Mast Height Raised | | | | Attachment | | | |
| Hydraulic Control Valve | | | | Directional Control | | | |
| Capacity | | | | Tires | | | |
| Mast Condition | | Not applicable | | Steering Pump Condition | | | |
| Mast Comments | | | | Steering Pump Comments | | | |
| Lift Cylinder Condition | | | | Hydraulic Pump Condition | | | |
| Lift Cylinder Comments | | | | Hydraulic Pump Comments | | | |
| Tilt Cylinder Condition | | Not applicable | | Hydraulic Motor Condition | | | |
| Tilt Cylinder Comments | | | | Hydraulic Motor Comments | | | |
| Carriage Condition | | Not applicable | | Control System Condition | | | |
| Carriage Comments | | | | Control System Comments | | | |
| Load Backrest Condition | | | | Drive Motor Condition | | | |
| Load Backrest Comments | | | | Drive Motor Comments | | | |
| Forks Condition | | | | Differential Condition | | | |
| Forks Comments | | | | Differential Comments | | | |
| Overhead Guard Condition | | Not applicable | | Drive Tires % Remaining | | 80 | |
| Overhead Guard Comments | | | | Drive Tires Condition | | | |
| | | | | Steer Tires % Remaining | | 80 | |
| Seat Condition | | Not applicable | | Steer Tires Condition | | | |
| Seat Comments | | | | Steer Axle Condition | | Not applicable | |
| | | | | Steer Axle Comments | | | |
| General Appearance Condition | | Fair | | Brakes Condition | | | |
| General Appearance Comments | | | | Brakes Comments | | | |
| General Comments | | | | Battery Present | | Yes | |
| Could use some good paint touch up but in all this is a solid unit | | | | Charger Present | | | |
| | | | | Electrical Condition | | | |
| | | | | Electrical Comments | | | |
| Inspector Company Name | | FSI | | Inspection Date | | 9/11/2019 9:32:41 AM | |
| Inspector Name | | Lyndi Sherwood | | | | | |

(* Legend: =Checked OK)





Jack 318
Serial # B287N02307P
Ship To Fresno



