CONDITION REPORT - ELECTRIC

Manufacturer	Model Year		Serial Number	
YALE MANUFACTURER	ERC060VG	2018	A968N18729S	
Mast	4 Stage (Quad)		Hours	N/a Inspected
Mast Height Lowered	98		Voltage	48 Volt
Mast Height Raised	294		Attachment	Side Shifter
Hydraulic Control Valve	3-Function		Directional Control	Lever
Capacity	6000		Tires	Cushion
Mast Condition	Inspected		Steering Pump Condition	Inspected
Mast Comments	1		Steering Pump Comments	1
Lift Cylinder Condition	Inspected		Hydraulic Pump Condition	Inspected
Lift Cylinder Comments	1		Hydraulic Pump Comments	1
Tilt Cylinder Condition	Inspected		Hydraulic Motor Condition	
Tilt Cylinder Comments	1		Hydraulic Motor Comments	
Carriage Condition	Inspected		Control System Condition	Inspected
Carriage Comments	Imspected.		Control System Comments	map • • • • • • • • • • • • • • • • • • •
Load Backrest Condition	Inspected			
Load Backrest Comments	mspected		Drive Motor Condition	Inspected
Forks Condition	Inspected		Drive Motor Comments	mspected
Forks Comments	mspected		Differential Condition	Inspected
			Differential Comments	Inspected
Overhead Guard Condition			Drive Tires % Remaining	90
Overhead Guard Comments			Drive Tires Condition	Inspected
			Steer Tires % Remaining	80
Seat Condition	Inspected		Steer Tires Condition	Inspected
Seat Comments	mspected		Steer Axle Condition	Inspected
			Steer Axle Comments	
General Appearance Condition	Fair		Brakes Condition	
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	Yes
Needs both rear light Clusters and work ligh	t replaced.		Charger Present	No
Treeds Sourreal light Glasters and Work light	in replaced.			
			Electrical Condition	Dead / low battery
			Electrical Comments	Wire harness cut
			-	

Inspector Company Name	PAPE	Inspection Date	7/19/2023 8:00:00 PM	
Inspector Name	ecarnes			







