

# CONDITION REPORT - ELECTRIC

<b>Manufacturer</b>	<b>Model</b>	<b>Year</b>	<b>Serial Number</b>
<b>YALE MANUFACTURER</b>	<b>MPB045VG</b>	<b>2018</b>	<b>A245N18439S</b>

Mast	Hours	565
Mast Height Lowered	Voltage	
Mast Height Raised	Attachment	
Hydraulic Control Valve	Directional Control	
Capacity	Tires	

Mast Condition	Not applicable	Steering Pump Condition	Inspected
Mast Comments		Steering Pump Comments	
Lift Cylinder Condition	Inspected	Hydraulic Pump Condition	Inspected
Lift Cylinder Comments		Hydraulic Pump Comments	
Tilt Cylinder Condition	Not applicable	Hydraulic Motor Condition	Inspected
Tilt Cylinder Comments		Hydraulic Motor Comments	
Carriage Condition	Not applicable	Control System Condition	Inspected
Carriage Comments		Control System Comments	
Load Backrest Condition	Not applicable	Drive Motor Condition	
Load Backrest Comments		Drive Motor Comments	
Forks Condition	Inspected	Differential Condition	Inspected
Forks Comments		Differential Comments	
Overhead Guard Condition	Not applicable	Drive Tires % Remaining	
Overhead Guard Comments		Drive Tires Condition	Inspected
Seat Condition	Not applicable	Steer Tires % Remaining	
Seat Comments		Steer Tires Condition	Not-Selected
		Steer Axle Condition	Inspected
General Appearance Condition	Fair	Steer Axle Comments	
General Appearance Comments		Brakes Condition	Inspected
		Brakes Comments	

General Comments

Solid Unit with lower hours

Battery Present	Yes
Charger Present	
Electrical Condition	Inspected
Electrical Comments	

Inspector Company Name	Inspection Date
Inspector Name	





