

CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number
YALE MANUFACTURER	MPE060-F	2015	C896N02852N

Mast	6 Lift Pallet	Hours	7569
Mast Height Lowered		Voltage	24 Volt
Mast Height Raised		Attachment	None
Hydraulic Control Valve		Directional Control	Lever
Capacity	6000	Tires	Cushion

Mast Condition	Not applicable	Steering Pump Condition	Not applicable
Mast Comments		Steering Pump Comments	
Lift Cylinder Condition		Hydraulic Pump Condition	Leaking
Lift Cylinder Comments		Hydraulic Pump Comments	Low on fluid
Tilt Cylinder Condition	Not applicable	Hydraulic Motor Condition	
Tilt Cylinder Comments		Hydraulic Motor Comments	
Carriage Condition		Control System Condition	
Carriage Comments		Control System Comments	
Load Backrest Condition	Not applicable	Drive Motor Condition	
Load Backrest Comments		Drive Motor Comments	
Forks Condition		Differential Condition	
Forks Comments		Differential Comments	
Overhead Guard Condition	Not applicable	Drive Tires % Remaining	60
Overhead Guard Comments		Drive Tires Condition	
Seat Condition	Not applicable	Steer Tires % Remaining	
Seat Comments		Steer Tires Condition	Not applicable
General Appearance Condition	Fair	Steer Axle Condition	Not applicable
General Appearance Comments		Steer Axle Comments	
General Comments		Brakes Condition	
		Brakes Comments	

The drive tire has cuts, load wheels need to be replaced, grab rail padding ripped/torn

Battery Present	Yes
Charger Present	No
Electrical Condition	Lights inoperable
Electrical Comments	Blown bulbs

Inspector Company Name	Pape material handling	Inspection Date	9/17/2023 8:00:00 PM
Inspector Name	curtisc		

(* Legend: =Checked OK)















