CONDITION REPORT - ELECTRIC

Mast Mast Height Lowered Mast Height Raised Hydraulic Control Valve Capacity Mast Condition Mast Comments	0XNT 20	14	Hours Voltage Attachment Directional Control	5136 36 Volt
Mast Height Lowered Mast Height Raised Hydraulic Control Valve Capacity Mast Condition			Voltage Attachment	
Mast Height Lowered Mast Height Raised Hydraulic Control Valve Capacity Mast Condition			Voltage Attachment	
Mast Height Raised Hydraulic Control Valve Capacity Mast Condition			Attachment	36 Volt
Hydraulic Control Valve Capacity Mast Condition				
Capacity Mast Condition			Directional Control	
Mast Condition				
			Tires	
			Steering Pump Condition	
			Steering Pump Comments	
Lift Cylinder Condition			Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition			Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition			Control System Condition	
Carriage Comments			Control System Comments	
Load Backrest Condition			,	
Load Backrest Comments			Drive Motor Condition	
Forks Condition			Drive Motor Comments	
Forks Comments			Differential Condition	
			Differential Comments	
Overhead Guard Condition			Drive Tires % Remaining	
Overhead Guard Comments			Drive Tires Condition	
			Steer Tires % Remaining	
Seat Condition D	amaged		Steer Tires Condition	Not-Selected
	RIPPED IN MAY SPOTS		Steer Axle Condition	
			Steer Axle Comments	
General Appearance Condition G	Good		Brakes Condition	
	Rust		Brakes Comments	
General Comments			Battery Present	Yes
SEAT RIPPED NO FIRE EXT - NOT SURE IF SPEC'D WITH ONE UPON DELIVERYDRIVE AND STEER TIRES NEED REPLACED - CRACKED AND CHUNKEDPAINT WORN DUE TO EVERY DAY WEAR		STEER TIRES	Charger Present	No
			Electrical Condition	
			Electrical Comments	

Inspector Company Name	BRIGGS EQUIPMENT	Inspection Date	6/11/2019 4:12:14 PM
Inspector Name	Christian Dano		























