## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model	Year	Serial Number		
YALE	OS030BF	2019	E826N05043T		
Mast			Hours	4701	
Mast Height Lowered	10		Voltage	24 Volt	
Mast Height Raised	25		Attachment		
Hydraulic Control Valve			Directional Control		
Capacity	2000		Tires	Non-Marking	
Mast Condition			Steering Pump Condition		
Mast Comments			Steering Pump Comments		
Lift Cylinder Condition			Hydraulic Pump Condition		
Lift Cylinder Comments			Hydraulic Pump Comments		
Tilt Cylinder Condition			Hydraulic Motor Condition		
Tilt Cylinder Comments			Hydraulic Motor Comments		
Carriage Condition			Control System Condition		
Carriage Comments			Control System Comments		
Load Backrest Condition			D. A. Martina O. a. 1985		
Load Backrest Comments			Drive Motor Condition		
Forks Condition			Drive Motor Comments		
Forks Comments			Differential Condition		
			Differential Comments		
Overhead Guard Condition			Drive Tires % Remaining	80	
Overhead Guard Comments			Drive Tires Condition		
			Steer Tires % Remaining		
Seat Condition			Steer Tires Condition	Not-Selected	
Seat Comments			Steer Axle Condition		
			Steer Axle Comments		
General Appearance Condition	Good		Brakes Condition		
General Appearance Comments			Brakes Comments		
General Comments			Battery Present	Yes	
dash panel missing drive unit doors mis	ssing hardware platform gate arms a	re damaged drive unit cover hardware	Charger Present	Yes	
missing			Floatrical Condition		
			Electrical Condition		
			Electrical Comments		

Inspector Company Name	eastern lift truck	Inspection Date	3/27/2023 8:56:00 PM	
Inspector Name	Tjcolvin			























