CONDITION REPORT - ELECTRIC

Inspector Company Name

Inspector Name

Manufacturer	Model	Year	Serial Number	
YALE MANUFACTURER	MPB045VG	2018	A245N18465S	
Mast			Hours	410
Mast Height Lowered			Voltage	
Mast Height Raised			Attachment	
Hydraulic Control Valve			Directional Control	
Capacity			Tires	
Mast Condition	Not applicable		Steering Pump Condition	Inspected
Mast Comments			Steering Pump Comments	
Lift Cylinder Condition	Inspected		Hydraulic Pump Condition	Inspected
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition	Not applicable		Hydraulic Motor Condition	Inspected
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition	Not applicable		Control System Condition	Inspected
Carriage Comments			Control System Comments	
Load Backrest Condition	Not applicable			
Load Backrest Comments			Drive Motor Condition	
Forks Condition	Inspected		Drive Motor Comments	
Forks Comments			Differential Condition	Inspected
			Differential Comments	
Overhead Guard Condition	Not applicable		Drive Tires % Remaining	
Overhead Guard Comments			Drive Tires Condition	Inspected
			Steer Tires % Remaining	
Seat Condition	Not applicable		Steer Tires Condition	Not-Selected
Seat Comments			Steer Axle Condition	Not applicable
			Steer Axle Comments	
General Appearance Condition	Fair		Brakes Condition	Inspected
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	Yes
Solid Unit low hours			Charger Present	
			Electrical Condition	Inspected
			Electrical Comments	
]	

Inspection Date



