CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number	
YALE	OS030BF	2019	E826N05025T	
Mast			Hours	4322
Mast Height Lowered	10		Voltage	24 Volt
Mast Height Raised	25		Attachment	
Hydraulic Control Valve			Directional Control	
Capacity	2000		Tires	Non-Marking
Mast Condition			Steering Pump Condition	
Mast Comments			Steering Pump Comments	
Lift Cylinder Condition			Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition			Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition			Control System Condition	
Carriage Comments			Control System Comments	
Load Backrest Condition				
Load Backrest Comments			Drive Motor Condition	
Forks Condition			Drive Motor Comments	
Forks Comments			Differential Condition	
			Differential Comments	
Overhead Guard Condition			Drive Tires % Remaining	45
			•	
Overhead Guard Comments			Drive Tires Condition	Chunked
			Steer Tires % Remaining	
Seat Condition			Steer Tires Condition	Not-Selected
Seat Comments			Steer Axle Condition	
			Steer Axle Comments	
General Appearance Condition	Good		Brakes Condition	
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	Yes
			Charger Present	Yes
operator cage damaged platform gate arn needs replace	ns are damaged drive unit cover dan	haged and missing hardware drive tire	Charger Fresent	165
			Electrical Condition	
			Electrical Comments	
<u> </u>				
Inspector Company Name	eastern lift truck		Inspection Date	3/27/2023 9:09:51 PM

Tjcolvin

Inspector Name























