CONDITION REPORT - INTERNAL COMBUSTION

Manufacturer	Model	Year	Serial Number	Corrected	
HYSTER COMPANY	S50FT	2012	F187V22341K	F187v22341k	
				40000	
Mast	3 Stage FFL (Triplex)		Hours	12996	
Mast Height Lowered	24		Fuel	LP Gas	
Mast Height Raised	189		Attachment	Side Shifter	
Hydraulic Control Valve	3-Function		Directional Control	Lever	
Capacity	5000		Tires	Cushion	
Mast Condition	Kicking / Rough movement		Engine	Other	
Mast Comments	Bad Rollers/Bearings		Engine Inspected Condition	Will not start	
Lift Cylinder Condition			Engine Inspected Comments	Further testing required	
Lift Cylinder Comments			Radiator Condition		
Tilt Cylinder Condition			Radiator Comments		
Tilt Cylinder Comments			Transmission/MDU Condition		
Carriage Condition	Tight / loose		Transmission/MDU Comments		
Carriage Comments	Impact damage				
Load Backrest Condition	Missing		Steering Pump Condition		
Load Backrest Comments	no backrest		Steering Pump Comments		
Forks Condition	Heels worn		Hydraulic Pump Condition		
Forks Comments	rusty		Hydraulic Pump Comments		
			Hydraulic Motor Condition		
Overhead Guard Condition			Hydraulic Motor Comments		
Overhead Guard Comments			Control System Condition		
Overnead Guard Comments			Control System Comments		
Seat Condition	Damaged		Control System Comments		
Seat Comments	holes and worn armrest		Differential Condition	Noisy	
Seat Comments	noies and worn armiest		Differential Comments	Low Fluid	
General Appearance Condition	Fair		Drive Tires % Remaining	1/2 worn	
			Drive Tires 76 Remaining Drive Tires Condition	Chunked	
General Appearance Comments	Sheet metal damage				
0			Steer Tires % Remaining	1/2worn	
General Comments			Steer Tires Condition	Not-Selected	
			Steer Axle Condition		
			I		
		Grabs			
			Brakes Comments	Banding wrapped over hub	
			Electrical Condition	Back-up alarm not functional	
			Electrical Comments	Missing items	
					

Inspector Company Name	liftech	Inspection Date	3/15/2019 11:05:17 AM
Inspector Name	BHayes		



Frained Operators and Mechanics Only



Read Operating Manual located on seat or in operators compartment

Failure to follow operating, inspection, and maintenance instructions can cause serious injury or death!

CAPACITY WITH MAST VERTICAL AND EQUIPPED AS SHOWN



Lift Truck Model S50FT

Senal No F187V2Z341K

Attachment, 977 mm (38 in) S5 Cry + 1067 mm (42 in) Forks

Truck Weight 4020 kg (8850 lb)

Tread Width 891 mm (35.1 in) Back Till 5.0 Degrees

Front Tire

21X7X15 Cushion Size

Real

1035510.5 Cushion

Pressure Load Height		Load Center		12-1-1	
MA	MUMIX	1000	Dim. B	Gim, C	P - Big
CAPACITY	No.	arto rom	930 mm	11 21 11	
2110 kg (4650 lb)	4800mitt (169-in)	(24 in)	(24 III)	Î	
	4350 mm	610 mm	650 mm		
2100 kg (asno to)		(171 3 10)	(25 m)		(\$10 to)



Check Operating Instructions

Basic Powershift Transmission









