CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number	Corrected
YALE MANUFACTURER	OS030EF	2018	D801N07129S	D801N07129S
Mast	3 Stage FFL (Triplex)		Hours	2321 Inspected
Mast Height Lowered			Voltage	24 Volt
Mast Height Raised	213		Attachment	
Hydraulic Control Valve			Directional Control	
Capacity	3000		Tires	
Mast Condition	Imamostod		Steering Pump Condition	
Mast Comments	Inspected		Steering Pump Comments	
Lift Cylinder Condition			Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition			Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition	Inspected		Control System Condition	Inspected
Carriage Comments	Inspected		Control System Comments	Поросос
Load Backrest Condition			,	
Load Backrest Comments			Drive Motor Condition	Inspected
Forks Condition	Inspected		Drive Motor Comments	mspected
Forks Comments	mspected		Differential Condition	
			Differential Comments	
Overhead Guard Condition	Inspected		Drive Tires % Remaining	
Overhead Guard Comments	шоресте		Drive Tires Condition	Inspected
			Steer Tires % Remaining	
Seat Condition			Steer Tires Condition	
Seat Comments			Steer Axle Condition	
			Steer Axle Comments	
General Appearance Condition	Good		Brakes Condition	
General Appearance Comments			Brakes Comments	
Concret Comments			Dottom: Dracent	Vee
General Comments			Battery Present	Yes
			Charger Present	
			Electrical Condition	
			Electrical Comments	
			Electrical Comments	
			_	

Inspector Company Name
Alta Material Handling
Inspector Name
Alta Material Handling
Inspector Date
12/8/2023 10:44:53 AM

(* Legend: I_{1115} Checked OK)











