## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model	Year	Serial Number	
YALE MANUFACTURER	ERC060VG	2018	A968N18727S	
Mast	4 Stage (Quad)		Hours	N/A Inspected
Mast Height Lowered	98		Voltage	48 Volt
Mast Height Raised	294		Attachment	Side Shifter
Hydraulic Control Valve	3-Function		Directional Control	Lever
Capacity	6000		Tires	Cushion
Mast Condition	Inspected		Steering Pump Condition	Inspected
Mast Comments	1		Steering Pump Comments	1
Lift Cylinder Condition	Inspected		Hydraulic Pump Condition	Inspected
Lift Cylinder Comments			Hydraulic Pump Comments	mepetite
Tilt Cylinder Condition	Inspected		Hydraulic Motor Condition	Inspected
Tilt Cylinder Comments	mspected		Hydraulic Motor Comments	hispected
Carriage Condition	Inspected		Control System Condition	Inspected
Carriage Comments	Inspected		Control System Comments	Inspected
Load Backrest Condition	Inspected			
Load Backrest Comments	Inspected		Drive Motor Condition	Inspected
Forks Condition	Inspected		Drive Motor Comments	Inspecieu
Forks Comments	Inspected		Differential Condition	Increated
			Differential Comments	Inspected
Overhead Guard Condition			Drive Tires % Remaining	85
Overhead Guard Comments			Drive Tires Condition	
Overneau Guard Commonie			Steer Tires % Remaining	Inspected 75
Seat Condition	1		Steer Tires % Remaining Steer Tires Condition	
Seat Condition	Inspected		Steer Fires Condition Steer Axle Condition	Inspected
Seat Comments			Steer Axle Condition Steer Axle Comments	Inspected
Condition	en da			
General Appearance Condition	Fair		Brakes Condition	Inspected
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	Yes
			Charger Present	No
Needs both rear light clusters replaced			Charger Freschi	
			Electrical Condition	Dead / low battery
			Electrical Comments	Wire harness cut
Inspector Company Name	PAPE		Inspection Date	7/19/2023 8:00:00 PM
Inspector company ramo			hispection bate	1/10/2020 0.00.00 F M

ecarnes

Inspector Name







