CONDITION REPORT - INTERNAL COMBUSTION

Manufacturer	Model Year	Serial Number	Corrected
HYSTER COMPANY	E40XN 2017	A269N03358R	A269N0358R
Mast	3 Stage FFL (Triplex)	Hours	15156
Mast Height Lowered	82	Fuel	
Mast Height Raised	187	Attachment	Carton Clamp
Hydraulic Control Valve	4-Function	Directional Control	Monotrol
Capacity		Tires	Cushion
Mast Condition		Engine	
Mast Comments		Engine Inspected Condition	
Lift Cylinder Condition		Engine Inspected Comments	
Lift Cylinder Comments		Radiator Condition	
Tilt Cylinder Condition		Radiator Comments	
Tilt Cylinder Comments		Transmission/MDU Condition	
Carriage Condition		Transmission/MDU Comments	
Carriage Comments			
Load Backrest Condition		Steering Pump Condition	
Load Backrest Comments		Steering Pump Comments	
Forks Condition		Hydraulic Pump Condition	
Forks Comments		Hydraulic Pump Comments	
T ORS Comments		· ·	
Querte and Querrel Quer differe		Hydraulic Motor Condition	
Overhead Guard Condition		Hydraulic Motor Comments	
Overhead Guard Comments		Control System Condition	
		Control System Comments	
Seat Condition	Damaged		
Seat Comments	ripped	Differential Condition	
		Differential Comments	
General Appearance Condition	Fair	Drive Tires % Remaining	
General Appearance Comments	Impact damage	Drive Tires Condition	
		Steer Tires % Remaining	80%
General Comments		Steer Tires Condition	
seat ripped, fourth function plastic handle broken, play in hydraulic valve linkage, battery dirty, trunion bushings worn, main lift hose chaffed, brake fluid dirty		Steer Axle Condition	
		Steer Axle Comments	
		Brakes Condition	
		Brakes Comments	
		Electrical Condition	
		Electrical Comments	
L			
Inspector Company Name	Eastern Lift Truck	Inspection Date	2/6/2023 1:37:53 PM
Inspector Company Name		inspection Date	210/2023 1.31.33 FIVI

jpellini

Inspector Name























