

**CONDITION REPORT - ELECTRIC**

<b>Manufacturer</b>	<b>Model</b>	<b>Year</b>	<b>Serial Number</b>
<b>YALE MANUFACTURER</b>	<b>MPE060-F</b>	<b>2015</b>	<b>C896N02860N</b>

Mast	6 Lift Pallet	Hours	2063
Mast Height Lowered		Voltage	24 Volt
Mast Height Raised		Attachment	
Hydraulic Control Valve		Directional Control	Lever
Capacity	6000	Tires	Cushion

Mast Condition		Steering Pump Condition	
Mast Comments		Steering Pump Comments	
Lift Cylinder Condition		Hydraulic Pump Condition	
Lift Cylinder Comments		Hydraulic Pump Comments	
Tilt Cylinder Condition		Hydraulic Motor Condition	
Tilt Cylinder Comments		Hydraulic Motor Comments	
Carriage Condition		Control System Condition	
Carriage Comments		Control System Comments	
Load Backrest Condition		Drive Motor Condition	
Load Backrest Comments		Drive Motor Comments	
Forks Condition		Differential Condition	
Forks Comments		Differential Comments	
Overhead Guard Condition		Drive Tires % Remaining	90
Overhead Guard Comments		Drive Tires Condition	
Seat Condition		Steer Tires % Remaining	
Seat Comments		Steer Tires Condition	
General Appearance Condition		Steer Axle Condition	
General Appearance Comments		Steer Axle Comments	
General Comments		Brakes Condition	
		Brakes Comments	
		Battery Present	Yes
		Charger Present	No
		Electrical Condition	
		Electrical Comments	

Inspector Company Name	Pape' Material and Handling	Inspection Date	9/17/2023 8:00:00 PM
Inspector Name	Joel Gaeta		

(\* Legend: =Checked OK)









