


## **CONDITION REPORT - INTERNAL COMBUSTION**

Manufacturer	Model	Year	Serial Number		
YALE MANUFACTURER	GC040VX	2012	A910V22103L		
Mast	3 Stage FFL (Triplex)		Hours	na Meter inoperable	
Mast Height Lowered			Fuel	LP Gas	
Mast Height Raised			Attachment	Other	
Hydraulic Control Valve	4-Function		Directional Control	Lever	
Capacity			Tires	Cushion	
Mast Condition	Needs chains/hoses		Engine	Mazda	
Mast Comments	Lift Chains stretched		Engine Inspected Condition		
Lift Cylinder Condition			Engine Inspected Comments		
Lift Cylinder Comments			Radiator Condition		
Tilt Cylinder Condition			Radiator Comments		
Tilt Cylinder Comments			Transmission/MDU Condition		
Carriage Condition			Transmission/MDU Comments		
Carriage Comments			Transmission, MDC Commission		
Load Backrest Condition	Not applicable		Steering Pump Condition		
Load Backrest Comments	Not applicable		Steering Pump Comments		
Forks Condition	Bent / warped / damaged		Hydraulic Pump Condition		
Forks Comments	worn out		Hydraulic Pump Comments		
Torks comments	wom out		Hydraulic Motor Condition		
Overhead Guard Condition			Hydraulic Motor Comments		
Overhead Guard Comments			Control System Condition		
Overnead Guard Comments			Control System Comments		
Seat Condition	Damaged		Control System Comments		
Seat Comments	needs seat		Differential Condition		
Seat Comments	neeus seat		Differential Comments		
General Appearance Condition			Drive Tires % Remaining	40	
General Appearance Comments			Drive Tires % Remaining  Drive Tires Condition	40	
General Appearance Comments				10	
General Comments			Steer Tires % Remaining Steer Tires Condition	10 Chunked	
				Chunked	
This truck does not run as it sits here in the yard. Can not do a correct inspection. installed new battery and motor appears to be locked up. Water in oil. tires wore out. All chains need replacing. Bad forks. Can not inspect not inspect any further unless vehicle is in running condition.			Steer Axle Condition		
			Steer Axle Comments		
			Brakes Condition		
			Brakes Comments		
			Electrical Condition		
			Electrical Comments		

Inspector Company Name	LIFTONE	Inspection Date	4/15/2019 12:58:06 PM
Inspector Name	ljames		









## Lift Truck Model GLC040VXNVSE08. Serial No. A910V22103L

chment: 978 mm (38.5 in) SS Crg + Cascade Rotator R30E-R

ack Weight 3890 kg (8570 lb)

ead Width 890 mm (35.1 in)

ack Tilt 5.0 Degrees

ire

Front

Size

21X7X15 Cushion

Pressure

Rear

16X5X10.5 Cushion

MAXIMUM

Load Height Dim. A

Load Center Dim. B , Dim. C

1360 kg 4800mn

0 mm | 610

mm 1 ---