CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number		
YALE	OS030BF	2019	E826N05037T		
				4000	
Mast			Hours	4923	
Mast Height Lowered	10		Voltage	24 Volt	
Mast Height Raised	25		Attachment		
Hydraulic Control Valve			Directional Control		
Capacity	2000		Tires	Non-Marking	
Mast Condition			Steering Pump Condition		
Mast Comments			Steering Pump Comments		
Lift Cylinder Condition			Hydraulic Pump Condition		
Lift Cylinder Comments			Hydraulic Pump Comments		
Tilt Cylinder Condition			Hydraulic Motor Condition		
Tilt Cylinder Comments			Hydraulic Motor Comments		
Carriage Condition			Control System Condition		
Carriage Comments			Control System Comments		
Load Backrest Condition			Control Cystem Comments		
Load Backrest Comments			Drive Motor Condition		
Forks Condition			Drive Motor Comments		
Forks Comments			Differential Condition		
Torks Comments			Differential Comments		
Overhead Guard Condition			Drive Tires % Remaining	80	
				80	
Overhead Guard Comments			Drive Tires Condition		
			Steer Tires % Remaining		
Seat Condition			Steer Tires Condition	Not-Selected	
Seat Comments			Steer Axle Condition		
			Steer Axle Comments		
General Appearance Condition	Good		Brakes Condition		
General Appearance Comments			Brakes Comments		
General Comments			Battery Present	Yes	
operator light and fan not working platforr	n gate arms damaged drive unit cover d	amaged and hardware missing	Charger Present	Yes	
drive unit doors missing hardware					
			Electrical Condition		
			Electrical Comments		
			_		
Inspector Company Name	eastern lift truck		Inspection Date	3/27/2023 9:25:58 PM	

Inspector Company Name Inspector Name eastern lift truck Tjcolvin



























