

CONDITION REPORT - ELECTRIC

Manufacturer	Model	Year	Serial Number
HYSTER COMPANY	N35ZR2	2015	E470N01946N

Mast	3 Stage FFL (Triplex)	Hours	8561
Mast Height Lowered	119	Voltage	36 Volt
Mast Height Raised	272	Attachment	
Hydraulic Control Valve	3-Function	Directional Control	Lever
Capacity	3500	Tires	Cushion

Mast Condition
 Mast Comments
 Lift Cylinder Condition
 Lift Cylinder Comments
 Tilt Cylinder Condition
 Tilt Cylinder Comments
 Carriage Condition
 Carriage Comments
 Load Backrest Condition
 Load Backrest Comments
 Forks Condition
 Forks Comments

Overhead Guard Condition
 Overhead Guard Comments

Seat Condition
 Seat Comments

General Appearance Condition
 General Appearance Comments

General Comments

Steering Pump Condition
 Steering Pump Comments
 Hydraulic Pump Condition
 Hydraulic Pump Comments
 Hydraulic Motor Condition
 Hydraulic Motor Comments
 Control System Condition
 Control System Comments

Drive Motor Condition
 Drive Motor Comments
 Differential Condition
 Differential Comments
 Drive Tires % Remaining
 Drive Tires Condition
 Steer Tires % Remaining
 Steer Tires Condition
 Steer Axle Condition
 Steer Axle Comments
 Brakes Condition
 Brakes Comments

Battery Present Yes
 Charger Present No

Electrical Condition
 Electrical Comments

90

Inspector Company Name	MH EQUIPMENT	Inspection Date	7/2/2019 10:04:00 AM
Inspector Name	Jmarzian		

(* Legend: =Checked OK)



39.305983 -84.474308
7/1/2019 11:52:07 AM



39.305983 -84.474308
7/1/2019 11:52:21 AM



39.305983 -84.474308
7/1/2019 11:51:39 AM



39.305983 -84.474308
7/1/2019 11:51:53 AM