CONDITION REPORT - ELECTRIC

Inspector Company Name

Inspector Name

Manufacturer	Model	Year	Serial Number		
YALE MANUFACTURER	MPB045VG	2018	A245N18460S		
Mast			Hours	535	
Mast Height Lowered			Voltage		
Mast Height Raised			Attachment		
Hydraulic Control Valve			Directional Control		
Capacity			Tires		
Mast Condition	Not applicable		Steering Pump Condition	Inspected	
Mast Comments			Steering Pump Comments		
Lift Cylinder Condition	Inspected		Hydraulic Pump Condition	Inspected	
Lift Cylinder Comments			Hydraulic Pump Comments		
Tilt Cylinder Condition	Not applicable		Hydraulic Motor Condition	Inspected	
Tilt Cylinder Comments			Hydraulic Motor Comments		
Carriage Condition	Not applicable		Control System Condition	Inspected	
Carriage Comments			Control System Comments		
Load Backrest Condition	Not applicable				
Load Backrest Comments			Drive Motor Condition		
Forks Condition	Inspected		Drive Motor Comments		
Forks Comments			Differential Condition	Inspected	
			Differential Comments		
Overhead Guard Condition	Not applicable		Drive Tires % Remaining		
Overhead Guard Comments			Drive Tires Condition	Inspected	
			Steer Tires % Remaining		
Seat Condition	Not applicable		Steer Tires Condition	Not-Selected	
Seat Comments			Steer Axle Condition	Not applicable	
			Steer Axle Comments		
General Appearance Condition	Fair		Brakes Condition	Inspected	
General Appearance Comments			Brakes Comments		
General Comments			Battery Present	Yes	
Solid Unit			Charger Present		
			Electrical Condition	Inspected	
			Electrical Comments		

Inspection Date





